



REPUBLIC OF THE PHILIPPINES
DEPARTMENT OF BUDGET AND MANAGEMENT
GENERAL SOLANO STREET, SAN MIGUEL, MANILA

REQUEST FOR QUOTATION

The Department of Budget and Management (DBM), through its Administrative Service (AS), will undertake a Small Value Procurement for the "Compressor Replacement and Leak Repair of Air Conditioning Unit", in accordance with Section 53.9 of the Implementing Rules and Regulations of Republic Act No. 9184.

- Name of Project : Compressor Replacement and Leak Repair of Air Conditioning Unit
- Approved Budget for the Contract : Two Hundred Fifty Two Thousand One Hundred Forty Pesos (P252,140.00)
- Specifications : See the Attached Annex "A" for specifications
- Location : 3/F DBM Building II, Gen. Solano St., San Miguel, Manila
- Delivery Date : Fifteen (15) calendar days upon receipt of the Notice to Proceed

Interested suppliers are required to submit their valid and current Mayor's Permit and PhilGEPS Registration Certificate, and price quotation (Annex "A").

Submission of quotation and eligibility documents is on or before 5:00p.m. of 3 March 2015 at the Administrative Service, Ground Floor, DBM Bldg. III, Gen. Solano St., San Miguel, Manila. Open submission may be submitted, manually or through facsimile at fax nos. 735-4979 / 735-1957.

For inquiry, you may contact us at tel. nos. 735-4979 or 490-1000 locals 3114, 3115 & 3117.

Very truly yours,

ATTY. SOFIA C. YANTO
Director, Administrative Service

PRICE QUOTATION FORM

 Date

The Administrative Service
 Department of Budget and Management
 Ground Floor, DBM Bldg. III, Gen. Solano St.,
 San Miguel, Manila

Sir/Madam:

After having carefully read and accepted the terms and conditions in the Request for Quotation, hereunder is our quotation/s for the item/s as follows:

Description/Specification	Scope of Work	Qty	Total Price
<ul style="list-style-type: none"> • Compressor Replacement and Leak Repair of Air Conditioning Unit • Air Conditioning Unit Details: <ul style="list-style-type: none"> ○ Brand: Hitachi ○ Type: VRF (Variable Refrigerant Flow), Multi System ○ Outdoor Unit Model: RA524FSN1 ○ Serial No: U47RB134 	<ul style="list-style-type: none"> • Supply and installation of brand new Inverter Compressor Motor; • Leak repair and testing; • Flushing the system with nitrogen gas; • Vacuuming the system; • Recharging the system with Freon gas to full charge; • Technical observation of the running operation of the unit 	1 lot	

(Amount in Words) _____

The above-quoted prices are inclusive of all costs and applicable taxes.

Very truly yours,

 Name/Signature of Representative

 Name of Company

 Contact No.