

Republic of the Philippines

DEPARTMENT OF BUDGET AND MANAGEMENT

Malacañang, Manila

Telephone Nos. 7354902 * 7351957

		PURCHASE O	RDER NO	. 2013-099			
Supplier: Address:		Isuzu Manila Date: June 19, 2013					
		1502 P. M. Guazon Street, Paco, Manila	Mode of Procurement: Shopping				
/ toures	1502 F. M. Guazon Street, Paco, Manila		Isuzu Crosswind - ZTD-537				
Tin:			COA				
Genti	lemen:					-	
Servic	e Ouoi	Please deliver the article(s) product(s)/supp tation dated June 10, 2013, subject to the Terr	lies/materials	listed below p	oriced in accordance	ce with your	
Place of	Delive	ery: DBM, Building III		erm: 15 days	ted at the back ne	reor:	
Date of Delivery: 15 days upon receipt of P.O.				Payment Term: Upon completion of delivery & acceptance			
Stock						, <u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>	
No.	Unit	Item and Description /Specificat	ion	Quantity	Unit Cost	AMOUNT	
		General Cleaning of Aircon unit & replace defect	ive parts				
	ľ	Parts:			į		
		Air compressor assembly				28,170.00	
	Expansion Valve (front & rear)				:	5,944.00	
i		Drier]	4,268.00	
		Evaporator				10,347.00	
		Rear aircon switch			ĺ	3,511.00	
		Battery				6,500.00	
		Freon		1		1,500.00	
		Labor				4,500.00	
	£					4,500.00	
]	1		
				1			
					1		
						•	
				!			
Total Ar	mount	In Words)				<u> </u>	
		usand Seven Hundred Forty Pesos				64,740.00	
in case	of failu	re to make the full delivery within the time specific	ed above, a per	alty of one-ten	th (1/10) of		
ne perce	ent (1%)	for every day of delay shall be imposed.					
				٧	ery truly yours,		
	Confor	me:			ATTY SON	FIA C. YANTO IW	
		JP PAULNO			//	nistrative Service	
		Signature over Printed Name of Supplier		!	Authori:	zed Official	
			_		(Represent	ting End User)	
inds Ava	ailability	Date Certified by:	OS No	2013-	· 10 - 10		
20103 AVC	anability	La ladio as	OS No :	10/02	10 10		
	ES	PERANZA Q. IGNACIO	Amount : Date :	- Y U	7, 140		
		Chief Accountant	Date .	4/	27/1 5		
stribution	n of Cop	ies:					
_		for the Supplier's Conforme			•		
/ Agen	icy's Cen	tral Supply and Property Section for file					

/ / COA Auditor